

ACCORD

on Fire and Building Safety in Bangladesh

Date: 12/12/2018

Subject: Accord Structural Safety Assessment for Vision Composite Knit Ltd. (10330).

For the attention of Factory Owner/Manager, Lead Brands, Active Brands & Union Colleagues,
We are writing to inform you of the Accord active and responsible brands at below factory.

Factory Name: Vision Composite Knit Ltd. (Accord Id: 10330)

Address: B-47, Purbo Rajshahi, Dhaka

The Accord conducted an initial structural assessment at this facility on **26/02/2014**. The Accord also conducted Follow-up structural inspections last on **17/10/2018**.

The factory has completed remediation on all structural issues identified in the Accord initial structural inspection report for this factory. Any color category associated with this factory is no longer valid, and the Accord is satisfied that general compliance with our structural safety standard is achieved.

Please note that this clearance is given based on the inspections conducted by the Accord and does not cover any modifications, extensions etc. which have taken place after the initial inspection unless specifically verified by the Accord. The factory must ensure the ongoing compliance with loading plans and maintenance to ensure the integrity of the building. The Accord reserves the right to ask further structural findings in the future.

This letter is a reference to structural findings only. It does not reference fire and electrical findings.

Sincerely,

Rob Wagon
Executive Director

Shikha Bangladesh Accord Foundation

ACCORD

on Fire and Building Safety in Bangladesh

Date: 05/12/2018

Subject: Accord Structural Safety Assessment for VISION APPARELS (PVT) LTD (9633)

For the attention of Factory Owner/Manager, Local Branch, Active Branch & Union Colleagues,
We are writing to inform you of the Accord active and responsible branch at below factory.

Factory Name: VISION APPARELS (PVT) LTD (Accord Id: 9633)

Address: Plot # M-4/3, Section-04, Mirpur, Dhaka

The Accord conducted an initial structural assessment of this facility on 05/05/2014. The Accord also conducted Follow-up structural inspections last on 03/12/2018.

The factory has completed remediation on all structural issues identified in the Accord initial structural inspection report for this factory. Any color category associated with this factory is no longer valid, and the Accord is satisfied that general compliance with our structural safety standard is achieved.

Please note that this clearance is given based on the inspections conducted by the Accord and does not cover any modifications, extensions etc. which have taken place after the initial inspection unless specifically verified by the Accord. The factory must ensure the ongoing compliance with loading plans and maintenance to ensure the integrity of the building. The Accord reserves the right to add further structural findings in the future.

This letter is a reference to structural findings only. It does not reference fire and electrical findings.

Sincerely,

Rob Hagan

Executive Director

Steering Bangladesh Accord Foundation

ACCORD

on Fire and Building Safety in Bangladesh

Date: 13/11/2018

Subject: Accord Structural Safety Assessment for Vision Garments Ltd. (9634).

*For the attention of Factory Owner/Manager, Lead Brand, Active Brands & Union Colleagues,
We are writing to inform you of the Accord active and responsible brands at below factory.*

Factory Name: Vision Garments Ltd. (Accord ID: 9634)

Address: B-47, Purbo Rajshahi, Savar, Gazipur

The Accord conducted an initial structural assessment at this facility on 26/02/2014. The Accord also conducted Follow-up structural inspections last on 27/10/2018.

The factory has completed remediation on all structural issues identified in the Accord initial structural inspection report for this factory. Any color category associated with this factory is no longer valid, and the Accord is satisfied that general compliance with our structural safety standard is achieved.

Please note that this clearance is given based on the inspections conducted by the Accord and does not cover any modifications, extensions etc. which have taken place after the initial inspection unless specifically verified by the Accord. The factory must ensure the ongoing compliance with loading plans and maintenance to ensure the integrity of the building. The Accord reserves the right to add further structural findings in the future.

This letter is a reference to structural findings only. It does not reference fire and electrical findings.

Sincerely,

Rob Wigns

Executive Director & Acting Chief Safety Inspector

Striking Bangladesh Accord Foundation